Utah Department of Environmental Quality Division of Drinking Water

Public Water System Inventory Report

Run Date: 08/04/2011 11:59 am

Gal/Min

PWS ID: UTAH09092 Name: PANGUITCH LAKE CHAPEL

Legal Contact CORP OF PRESIDING BISHOP- LDS CHL Rating: Approved

ROY BENSON MCDANIEL Rating Date: 10/25/2010

Address: 50 E NORTH TEMPLE ST, RM 1205 Activity Status: Active

SALT LAKE CITY, UT 84150-6320

Phone Number: 801-240-4656

City Served (Area):

County: GARFIELD COUNTY

System Type: Non-community

Last Inv Update: 05/16/2011

Avg Daily Prod:

Activity Status Cd: Active Last Snty Srv Dt: 12/31/2010 Total Dsgn Cap:
Population: 50 Surveyor: KATE JOHNSON Total Emerg Cap:

Oper Period: 5/15 to 9/30

Contacts

Contact		Phone Numbers							
Type	Name	Title	Office	Emergency	Email Address				
AC	MCDANIEL, ROY BENSON	ENGINEER	801-240-4656	801-446-8498	mcdanielrb@ldschurch .org				

Service Connections

Connection Type	Meter Type Code	Meter Size	Number Connections	
Combined	Unknown	0	1	
			1 Total Sv	vc Connections

Storage

Total Storage: 0 GAL Number of Units: 1 Adequate Capacity: NO

No.	Name	Туре	Effective Volume	Constr Matrl	Overflow Elev	Activity Status	Press'd
ST001	CHAPEL HYDROPNEUMATIC	Hydropneuma				Α	YES

Distribution System

Pump Type	Total Dyn Head ft H2O P.S.I.		Pressure Adequate	Cross Connection	Auhority Statement
			No		

Sources

No.	Source Name	Activity Status	Source Type	Well Dia.	Safe Yield *	Pump Capacity	Data On File	Water Type	Availability	Period of Operation	Grnd Wtr Indicator
WS001	CHAPEL WELL	Active	WL	6	30 GPM	0 GPM	Yes	GW	Seasonal	5/1 to 9/30	

^{*}Reports measured flow for wells, approved design capacity for all other sources.